
Form No. 101977



SPX Corporation 5885 11th Street Rockford, IL 61109-3699 USA Tech. Services: (800) 477-8326 Fax: (800) 765-8326 Order Entry: (800) 541-1418 Fax: (800) 288-7031 Parts List for:

RH1505


Internet Address: http://www.powerteam.com



DANGER: To help avoid possible serious personal injury or death,

In the event that the cylinder retract port is ever restricted or plugged, a double-acting cylinder relief valve will help prevent excessive pressure from building in the cylinder. DO NOT attempt to adjust or service this relief valve! If oil leakage is detected from this relief valve, discontinue use of the cylinder immediately and contact Power Team Technical Services. <u>Only</u> Power Team Authorized Hydraulic Service Centers should service this relief valve.

ltem No.		No. ReqÕ	d Description		
1 2	351859 59234OR9		Decal, Tradename (Power Team) Handle, Cylinder Lift Decal, Warning	Sheet No.	1 of 1
3	203908			Rev. 2	Date: 22 Mar. 1999



No.	No.	Req'd	Description	No.	No.	Req'd	Description
1	37287	1	Insert, Plain	11	*16313	1	T-seal (7.00 x 6.50 x .36 L)
2	37288	1	Insert, Serrated	12	*16316	1	U-cup (3.75 x 3.25 x .38 H)
3	*10295	1	O-ring (2.50 x 2.25 Nitrile)	13	*†19166	1	Washer, Backup (3.50 x 3.25)
4	*10297	2	O-ring (3.50 x 3.25 Nitrile)	14	36406	1	Pipe, Stand (Bottom out and back off
5	51043	1	Nut, Retainer (10-32)				1/8 revolution before adding set
6	*207593	1	Wiper, Rod (5.94 x 5.50 URE)				screw; Molykote all thds.)
7	*†19176	1	Washer, Backup (7.00 x 6.75)	15	10556	1	Screw, Set (1/4-20 x 1/4;
8	*16317	1	O-ring (7.00 x 6.75 Nitrile)				See NOTE below
9	*16315	1	U-cup (6.00 x 5.50 x .56 H)	16	9796	2	Coupler, Quick Cylinder Half
10			Wiper, Rod (3.63 x 3.25 URE)	17	65995	1	Body, Cylinder
-				18	51044	1	Piston

Part numbers marked with an asterisk (*) are contained in Repair Kit No. 300154. Part numbers marked with a dagger (†) are contained in Viton Seal Kit No. 300228.

NOTE: Cylinders built after 1-1-99 do not use this set screw to lock the standpipe and cylinder body together. Loctite 242 is used on last 2-3 standpipe threads only!

Note: Shaded areas reflect last revision(s) made to this form.

Item

Refer to any operating instructions included with this product for detailed information about operation, testing, disassembly, reassembly, and preventive maintenance.

Items found in this parts list have been carefully tested and selected. Therefore: Use only genuine Power Team replacement parts!

Additional questions can be directed to our Technical Services Department.