

SPX Corporation
5885 11th Street
Rockford, IL 61109-3699 USA

Tech. Services: (800) 477-8326
Fax: (800) 765-8326
Order Entry: (800) 541-1418
Fax: (800) 288-7031

Internet Address:
<http://www.powerteam.com>


**Parts List and Assembly
Instructions for:**

350376

TILT SADDLE CAP ASSEMBLY

FOR 55 TON "C" & "RA" SERIES CYLINDERS

Item No.	Part No.	No. Req'd	Description
1	215757	1	Hex. Soc. Hd. Screw
2	350252	1	Swivel Cap
3	16112	2	Rd. Hd. Machine Screw
4	350254	1	Tilt Saddle Base



ASSEMBLY

1. Mount tilt saddle base to cylinder piston with two round head machine screws.
2. Position swivel cap on base and tilt until lip on swivel cap contacts the base.
3. Thread in self-locking flat head screw. DO NOT overtighten. Swivel cap should swivel freely, and lip on swivel cap should always contact the base at maximum tilt angle.

Note: Shaded areas reflect last revision(s) made to this form.